

# Technical *Info*

## Changes to the CT 1035 K1 / CT 1035 K2 tension pulley – Renault 1.5 dCi Nissan 1.5 dCi, Suzuki 1.5 DDIS

### Problem:

The tension pulley supplied in the kit is designed differently from the pulley previously installed in the vehicle. (Fig.1)

### Cause:

There is an alternative design (Fig. 2)  
This is supplied with the same screw and can be installed according to the vehicle manufacturer's specifications.

### Solution:

Despite its different design, the tension pulley can be used for all the vehicles specified in the catalog.

Fig. 1  
Previous design



Fig. 2  
Alternative design



Comparison of base plates

