

31-14 610 0014/HD 51396-SMG-E05

HD



Control arm bushing to fit Honda Civic VIII (FN)









Rubber bearing does not provide enough cornering force and can wear out

Effect

Steering play, accurate lateral guidance no longer possible

An optimised component with a longer service life

outer sleeve





Solution

Reinforcement of the critical rubber

dimensions for enhanced bonding of the inner control arm mount to the

Wulf Gaertner Autoparts AG • L06.2013 Merkurring 111 • 22143 Hamburg • Germany contact@meyle.com • www.meyle.com