



MEYLE No. 300 333 2104/HD
Reference No. 33 32 6 770 786

Subframe mount, axle carrier to fit BMW E36, E46, E83, E85, E86



as OE



Problem

Premature wear causing excessive free play in the rear trailing arm bushings

Effect

- Comprised rear suspension control and responsiveness
- Loss of driving comfort and safety



Solution




- Use of a radial expansion bushing with a slotted outer sleeve comparable in performance to the BMW sports version
- Higher bushing pre-load

Advantage

Firm and positive rear suspension response and a longer expected service life

as OE



MEYLE-HD version

