

## Different versions of tensioning pulley 531 0547 10

## Manufacturer:

Dacia, Nissan, Renault, Suzuki

## Models:

Nissan

• Dacia	Logan
• Nissan	Almera II, Kubistar,
• Renault	Micra, Note, Qashqai, Tiida Clio II, Clio III, Kangoo, Laguna III, Megan II Modus, Scenic II,
	Grand Scenic, Thalia,
C. C.	Twingo
• Suzuki	Jimny
Engine:	1.5 dCi, 1.5 DDiS
LuK AS Part No.:	531 0547 10
OE-No.:	
• Dacia / Renault	82 00 585 574

82 00 102 941

13070-BN700



Fig. 1: 531 0547 10 (Version 1)

The three diagrams show the tensioning pulley **531 0547 10** in two different versions.

The major differences are the seals of the ball bearing, the base plate and the cam. All versions are supplied with the same screw and can be assembled in accordance with the instructions provided by the manufacturer.



Fig. 2: 531 0547 10 (Version 2)



Fig. 3: 531 0547 10 (back side)

Appropriate spare parts can be found in our on-line catalogue at www.Schaeffler-Aftermarket.com or at www.RepXpert.com.

Issued 05.2009 INA 0031 Technical subject to change © 2009 Schaeffler Automotive Aftermarket oHG



 For further information:

 Phone:
 +44 (0) 14 32 264 264\*

 Fax:
 +44 (0) 14 32 375 760

 Info@LuK-AS.co.uk
 www.Schaeffler-Aftermarket.com

 \* Calls from within the UK 08457 00100

## Note:

Despite the different versions, the tensioning pulley can be used on all the vehicles listed in the catalogue.