

Conductor Plate Kit for automatic transmissions

febi no. 36542 Repl. no. 140 270 11 61 S1

Fits all Mercedes-Benz 5-gear automatic transmissions.

The sensors of the conductor plate stick together due to deposits in the automatic transmission fluid. This results in gear change malfunctions in the transmission.



Please note!

Always replace the plug at the same time as replacing the conductor plate. Otherwise leaks may occur at the outlet from the conductor plate. As a result the oil perforates the seal and can therefore get into the automatic transmission control unit via the wiring loom and lead to damage in the control unit.

For this reason, febi bilstein supplies the complete kit febi 36542 which includes both the conductor plate febi 32342 and also the plug for automatic transmissions febi 36332. This combination enables a professional repair and avoids potential complaints. That saves time and money for both workshop and customer!



GB





febi no. 36542

febi bilstein also supplies the conductor plate and plug separately.

Simply ask for spare parts by febi bilstein. The complete range can be found at: www.febi.com febi no. 32342



febi no. 36332



Ferdinand Bilstein GmbH + Co. KG

Wilhelmstr. 47 | 58256 Ennepetal | Germany Tel. +49 2333 911-0 Fax +49 2333 911-444 E-Mail info@febi.com

ebi bilstein

www.febi.com