



febi

Tip

Quick and easy repair
of the rear axle with the

febi seal sets for AP axles suited for Mercedes Benz Actros, Atego and Axor

**Rear axle BM 748.210-220, 222,
223, 230, 231, 234 bis 248, 260-263,
268-275**

e.g. febi number 21980

Comparison number 940 350 08 35

With this extensive product range febi bilstein takes a leading position in the IAM:
numerous seal sets suited for Mercedes trucks with and without ABS.

Our extra service:

The specification of the SA number facilitates the assignment to the correct
vehicle type.

Another advantage:

The febi pressure ring is hardened. To avoid damages of the rotary shaft seal
during the assembly the febi pressure ring provides of a bevelled edge.

Please ask your febi partner for spare parts by febi bilstein!

You will also find all spare parts at www.febi.com



febi no.
21980

with ABS

**Additional repair
kits with ABS:
febi no. 21946,
21948, 21976,
21978, 21980**



febi no. 04454/04455



febi no.
21979

without ABS

**Additional repair
kits without ABS:
febi no. 21947,
21949, 21977,
21979, 21982**

Valid as of 01/06

www.febi.com

Ferdinand Bilstein GmbH + Co. KG · Wilhelmstr. 47 · 58256 Ennepetal
Fon +49 2333 911-0 · Fax +49 2333 911-444 · info@febi.com

bilstein group

