

**Now available: MEYLE 100 151 0000/S – Centre bearing repair kit suitable for the VW Touareg and Porsche Cayenne**

## Complete cardan shaft change to replace defective centre bearing? – Not with MEYLE!

The task of the centre bearing is to position the cardan shaft and absorb vibration. Premium-class SUVs fitted with a high-torque engine are subject to particularly high levels of stress. As the most vulnerable part of the bearing, the rubber component is likely to become brittle and crack under excessive strain. A defective centre bearing must be replaced immediately. However, authorised VAG shops do not offer the bearing separately, making replacement of the entire cardan shaft unavoidable – a procedure involving considerable costs!

The MEYLE centre bearing repair kit offers a swift, cost-effective alternative paired with unproblematic replacement. The kit includes the bearing, rubber boot, clamp ring and grease complemented by step-by-step fitting instructions to ensure full-service repair.



<b>MEYLE no.: 100 151 0000/S</b>	Centre bearing repair kit
<b>MEYLE no.: 100 152 1001</b>	Flex disc repair kit incl. mounting material
<b>MEYLE no.: 100 152 2001</b>	Full-service cardan shaft repair kit incl. mounting material

### The MEYLE engineers recommend:

To avoid repeated repairs and additional costs always replace the flex disc along with the centre bearing. It's just as easy with the MEYLE repair kit 100 152 1001 containing the flex disc and corresponding mounting parts.

### Also available is a full-service kit version:

The MEYLE repair kit 100 152 2001 which includes the centre bearing, flex disc, stretch bolts and mounting parts.

