

Service Information XZS182

Different design - same function

The TRW design, for the parts shown below, is different to the OE design. Whilst the visual appearance has changed, the fitting/function is the same.

Both designs are suitable to repair/maintain the brake.














Affected part numbers:

- GSK1264
- GSK1228